


This report provided free of charge by: Silicon Valley Prestige Motors LLC 2130 N Arrowhead Ave Ste 110C3, San Bernardino, CA 92405 (650) 338-7219



CARFAX Vehicle	e History	Report [™]	US \$39.99
2003 SAAB 9-3 ARC VIN: YS3FD46Y431055898 SEDAN 4 DR 2.0L I4 F GASOLINE FRONT WHEEL DRIVE	1	Damage reported: minor damage Image reported: minor damage <t< td=""><td></td></t<>	
		3 Previous owners	Sec.
	Ŕ	At least 1 open recall	
	\times	21 Service history records	
This CARFAX Report Provided by: Silicon Valley Prestige Motors LLC	79128	199,859 Last reported odometer reading	FOR

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 9/30/21 at 12:50:24 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Ownership History The number of owners is estimated	🔓 Owner 1	📥 Owner 2	🔓 Owner 3
Year purchased	2003	2011	2012
Type of owner	Personal	Personal	Personal
Estimated length of ownership	7 yrs. 9 mo.	1 year	9 yrs. 1 mo.
Owned in the following states/provinces	Illinois	Minnesota	Minnesota, Colorado
Estimated miles driven per year	17,117/yr		6,121/yr
Last reported odometer reading	134,229	140,231	199,859



	No Problem	No Problem	No Problem
Not Actual Mileage Exceeds Mechanical Limits	Guaranteed No Problem	Guaranteed No Problem	Guaranteed No Problem

BUYE	ACT
CARI	ТΑх
El	1

GUARANTEED - None of these major title problems were reported by a state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, CARFAX will buy this vehicle back. Register | View Terms | View Certificate

CARFAX Additional History Not all accidents / issues are reported to CARFAX	📥 Owner 1	💄 Owner 2	💄 Owner 3
Total Loss No total loss reported to CARFAX.	No Issues Reported	No Issues Reported	No Issues Reported
Structural Damage CARFAX recommends that you have this vehicle inspected by a collision repair specialist.	No Issues Reported	No Issues Reported	No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	No Issues Reported	No Issues Reported	No Issues Reported
Odometer Check No indication of an odometer rollback.	No Issues Indicated	No Issues Indicated	No Issues Indicated
Accident / Damage Damage reported: 08/19/2019.	No Issues Reported	No Issues Reported	Minor Damage
Manufacturer Recall At least 1 manufacturer recall requires service. Locate an authorized <u>Saab dealer</u> to obtain more information about this recall.	Recall Reported	No New Recalls Reported	No New Recalls Reported
Basic Warranty <u>Original warranty</u> estimated to have expired.	Warranty Expired	Warranty Expired	Warranty Expired

CARFAX Detailed History

Owner Purchase	-				Personal Vehicle 17,117 mi/yr
Date	Mileage	Source		Comments	
06/13/2003		US Customs		Vehicle exported from - Sweden and imported to - Newark, NJ	
06/24/2003		Dealer Inventory Illinois		Vehicle sold	
06/24/2003		Illinois Motor Vehicle Dept. Palos Heights, IL		Titled or registered as personal vehicle	
08/15/2003	7	Illinois Motor Vehicle Dept. Palos Heights, IL Title #T3227648213		Title issued or updated - First owner reported	
09/08/2003	3,670	Service Facility	\times	Vehicle serviced	
09/08/2003		Patrick Dealer Group Schaumburg, IL patrickcars.com	Ж	Vehicle serviced	
		 ★ 4.5 / 5.0 <u>174 Verified Reviews</u> ♥ 1,321 Customer Favorites 			
09/24/2003	4,926	Service Facility	×	Vehicle serviced	
09/24/2003		Patrick Dealer Group Schaumburg, IL patrickcars.com	×	Vehicle serviced	
		 ★ 4.5 / 5.0 <u>174 Verified Reviews</u> ♥ 1,321 Customer Favorites 			
04/13/2004	14,502	Service Facility	×	Vehicle serviced - Recommended maintenance performed - Window switch replaced	
04/13/2004		Chevy Exchange Lake Bluff, IL 847-615-1111 chevyexchange.com 4.7 / 5.0 <u>167 Verified Reviews</u>	×	Vehicle serviced - Recommended maintenance performed - Window switch replaced	

10/11/2004		Chevy Exchange Lake Bluff, IL	×	Vehicle serviced - Headlight bulb(s) replaced
		847-615-1111 chevyexchange.com		
		★ 4.7 / 5.0 <u>167 Verified Reviews</u> 🕏		
		93,814 Customer Favorites		
0/28/2004	25,398	Service Facility	\times	Vehicle serviced - Vehicle washed/detailed
0/28/2004		Patrick Dealer Group Schaumburg, IL patrickcars.com 4.5 / 5.0 <u>174 Verified Reviews</u>	×	Vehicle serviced
		 1,321 Customer Favorites 		
0/29/2004		Chevy Exchange	• •	Vehicle serviced
0/23/2004		Lake Bluff, IL 847-615-1111 chevyexchange.com	×	
		 ★ 4.7 / 5.0 <u>167 Verified Reviews</u> ♥ 3,814 Customer Favorites 		
03/10/2006		Saab Cars North America		Manufacturer recall/service bulletin issued - Recall #15019
				- RECALL15019-REPLACEBRAKESERVOVACUUMPIPE
				Locate an authorized Saab Warranty Service Provider to obtain more information about this recall - Learn more about this recall
-		when minimum stopping distance is required, new redesigned check valve. This service will b General Motors		d free of charge. Manufacturer Safety recall issued
Remedy: Deale		new redesigned check valve. This service will h		d free of charge.
		new redesigned check valve. This service will h		d free of charge. Manufacturer Safety recall issued - NHTSA #05V236 - Recall #15019 - RECALL 15019 - REPLACE BRAKE SERVO VACUUM PIPE
Description: Co	ers will install a r	new redesigned check valve. This service will b General Motors	be performe	d free of charge. Manufacturer Safety recall issued - NHTSA #05V236 - Recall #15019 - RECALL 15019 - REPLACE BRAKE SERVO VACUUM PIPE - Status: Remedy Available Locate an authorized General Motors dealer to obtain more information about this recall. - Learn more about this recall
Description: Ce from exposure	ers will install a r ertain sport seda to elevated tem	new redesigned check valve. This service will the General Motors General Motors	pe performe	d free of charge. Manufacturer Safety recall issued - NHTSA #05V236 - Recall #15019 - RECALL 15019 - REPLACE BRAKE SERVO VACUUM PIPE - Status: Remedy Available Locate an authorized General Motors dealer to obtain more information about this recall. - Learn more about this recall n a vacuum pipe check valve for the brake booster that may fail a assist, usually with little or no warning.
Description: Co from exposure If this condition	ers will install a r ertain sport seda to elevated tem n were to occur	new redesigned check valve. This service will the General Motors General Motors an and convertible passenger vehicles were priperatures. This could result in sudden loss of when minimum stopping distance is required,	roduced with power brake a crash cou	d free of charge. Manufacturer Safety recall issued - NHTSA #05V236 - Recall #15019 - RECALL 15019 - REPLACE BRAKE SERVO VACUUM PIPE - Status: Remedy Available Locate an authorized General Motors dealer to obtain more information about this recall. - Learn more about this recall n a vacuum pipe check valve for the brake booster that may fail e assist, usually with little or no warning. Id occur.
Description: Co from exposure If this condition	ers will install a r ertain sport seda to elevated tem n were to occur	new redesigned check valve. This service will the General Motors General Motors	roduced with power brake a crash cou	d free of charge. Manufacturer Safety recall issued - NHTSA #05V236 - Recall #15019 - RECALL 15019 - REPLACE BRAKE SERVO VACUUM PIPE - Status: Remedy Available Locate an authorized General Motors dealer to obtain more information about this recall. - Learn more about this recall n a vacuum pipe check valve for the brake booster that may fail e assist, usually with little or no warning. Id occur.
Description: Ce from exposure If this condition Remedy: Deale	ers will install a r ertain sport seda to elevated tem n were to occur	new redesigned check valve. This service will the General Motors General Motors an and convertible passenger vehicles were priperatures. This could result in sudden loss of when minimum stopping distance is required,	roduced with power brake a crash cou	d free of charge. Manufacturer Safety recall issued - NHTSA #05V236 - Recall #15019 - RECALL 15019 - REPLACE BRAKE SERVO VACUUM PIPE - Status: Remedy Available Locate an authorized General Motors dealer to obtain more information about this recall. - Learn more about this recall n a vacuum pipe check valve for the brake booster that may fail e assist, usually with little or no warning. Id occur.
D3/17/2006 Description: Ce from exposure If this condition	ertain sport seda to elevated tem n were to occur	an and convertible passenger vehicles were pr peratures. This could result in sudden loss of when minimum stopping distance is required, new redesigned check valve. This service will b Illinois Inspection Station	roduced with power brake a crash cou	d free of charge. Manufacturer Safety recall issued - NHTSA #05V236 - Recall #15019 - RECALL 15019 - REPLACE BRAKE SERVO VACUUM PIPE - Status: Remedy Available Locate an authorized General Motors dealer to obtain more information about this recall. - Learn more about this recall n a vacuum pipe check valve for the brake booster that may fail e assist, usually with little or no warning. Id occur. d free of charge.
Description: Ce from exposure If this condition Remedy: Deale	ertain sport seda to elevated tem n were to occur	an and convertible passenger vehicles were pr peratures. This could result in sudden loss of when minimum stopping distance is required, new redesigned check valve. This service will l Illinois Inspection Station Harvey, IL Rizza Cadillac Buick GMC Tinley Park, IL 708-429-6600 rizzabuickcadillacgmc.com/	roduced with power brake a crash cou	d free of charge. Manufacturer Safety recall issued - NHTSA #05V236 - Recall #15019 - RECALL 15019 - REPLACE BRAKE SERVO VACUUM PIPE - Status: Remedy Available Locate an authorized General Motors dealer to obtain more information about this recall Learn more about this recall n a vacuum pipe check valve for the brake booster that may fail e assist, usually with little or no warning. ld occur. d free of charge. Passed emissions inspection
Description: Ce from exposure If this condition Remedy: Deale 03/03/2007	ertain sport seda to elevated tem n were to occur	an and convertible passenger vehicles were pr peratures. This could result in sudden loss of when minimum stopping distance is required, new redesigned check valve. This service will t Illinois Inspection Station Harvey, IL Rizza Cadillac Buick GMC Tinley Park, IL 708-429-6600 rizzabuickcadillacgmc.com/	roduced with power brake a crash cou	d free of charge. Manufacturer Safety recall issued - NHTSA #05V236 - Recall #15019 - RECALL 15019 - REPLACE BRAKE SERVO VACUUM PIPE - Status: Remedy Available Locate an authorized General Motors dealer to obtain more information about this recall Learn more about this recall n a vacuum pipe check valve for the brake booster that may fail e assist, usually with little or no warning. ld occur. d free of charge. Passed emissions inspection
Description: Ce from exposure If this condition Remedy: Deale	ers will install a r ertain sport seda to elevated tem n were to occur ers will install a r 68,000	an and convertible passenger vehicles were pr peratures. This could result in sudden loss of when minimum stopping distance is required, new redesigned check valve. This service will t Illinois Inspection Station Harvey, IL Rizza Cadillac Buick GMC Tinley Park, IL 708-429-6600 rizzabuickcadillacgmc.com/	roduced with power brake a crash cou	d free of charge. Manufacturer Safety recall issued - NHTSA #05V236 - Recall #15019 - RECALL 15019 - REPLACE BRAKE SERVO VACUUM PIPE - Status: Remedy Available Locate an authorized General Motors dealer to obtain more information about this recall Learn more about this recall n a vacuum pipe check valve for the brake booster that may fail e assist, usually with little or no warning. Id occur. d free of charge. Passed emissions inspection Vehicle serviced
Description: Co from exposure If this condition Remedy: Deale 03/03/2007 03/12/2009	ers will install a r ertain sport seda to elevated tem n were to occur ers will install a r 68,000	an and convertible passenger vehicles were pr peratures. This could result in sudden loss of when minimum stopping distance is required, new redesigned check valve. This service will the Illinois Inspection Station Harvey, IL Rizza Cadillac Buick GMC Tinley Park, IL 708-429-6600 rizzabuickcadillacgmc.com/	roduced with power brake a crash cou	d free of charge. Manufacturer Safety recall issued - NHTSA #05V236 - Recall #15019 - RECALL 15019 - REPLACE BRAKE SERVO VACUUM PIPE - Status: Remedy Available Locate an authorized General Motors dealer to obtain more information about this recall - Learn more about this recall n a vacuum pipe check valve for the brake booster that may fail e assist, usually with little or no warning. Id occur. d free of charge. Passed emissions inspection Vehicle serviced Passed emissions inspection

1, 10:50 PM		CARFAX Vehicle History	Report for this	2003 SAAB 9-3 ARC: YS3FD46Y431055898	
04/04/2011	133,054	Auto Auction		Listed as a dealer vehicle - Vehicle sold	
				Millions of used vehicles are bought and sold at aud every year.	ction
04/05/2011		BMW of Orland Park Orland Park, IL 708-460-4545 bmwoforlandpark.com	×	Vehicle serviced - Vehicle washed/detailed	
04/15/2011		Andrews Inc. Of Princeton Princeton, MN 763-633-7222 andrewsautohouse.com		Vehicle offered for sale	
05/03/2011	133,212	Andrews Inc. Of Princeton Princeton, MN 763-389-3805 saabpros.com	×	Vehicle serviced	
05/12/2011	133,234	Andrews Inc. Of Princeton Princeton, MN 763-633-7222 andrewsautohouse.com		Vehicle sold	
06/17/2011	134,229	Andrews Inc. Of Princeton Princeton, MN 763-389-3805 saabpros.com	×	Vehicle serviced	
Owner 2 Purchase					sonal Vehicl
Date	Mileage	Source		Comments	
08/08/2011		Minnesota Motor Vehicle Dept. Saint Paul, MN Title #H2200V124		Vehicle purchase reported - Title or registration issued - New owner reported - Vehicle color noted as Gray	
01/30/2012	140,231	Andrews Inc. Of Princeton Princeton, MN 763-389-3805 saabpros.com	×	Vehicle serviced - Light bulb(s) replaced	
04/11/2012		Minnesota Motor Vehicle Dept. Saint Paul, MN Title #H2200V124		Registration issued or renewed - Vehicle color noted as Gray	
Owner S Purchase		Low mileage! This owner drove lindustry average of 15,000 miles		Pers	onal Vehicl 6,121 mi/y
Date	Mileage	Source		Comments	
08/08/2012		Colorado Motor Vehicle Dept.		Vehicle purchase reported	
08/08/2012		Minnesota Motor Vehicle Dept. Saint Paul, MN Title #C2210Q487		Title issued or updated - New owner reported - Loan or lien reported - Vehicle color noted as Gray	
01/10/2013		Andrews Inc. Of Princeton Princeton, MN 763-389-3805 saabpros.com	×	Vehicle serviced - Tires rotated - Rear shock absorber(s) replaced - Airbag computer/module replaced	

01/10/2013		Andrews Inc. Of Princeton Princeton, MN 763-389-3805 saabpros.com	్×	Vehicle serviced - Tires rotated - Rear shock absorber(s) replaced - Airbag computer/module replaced - Battery replaced - Sway bar link(s) replaced
02/20/2013	149,882	Andrews Inc. Of Princeton Princeton, MN 763-389-3805 saabpros.com	℅	Vehicle serviced
04/11/2013		Minnesota Motor Vehicle Dept. Saint Paul, MN Title #C2210Q487		Registration issued or renewed - Loan or lien reported - Vehicle color noted as Gray
04/24/2014		Minnesota Motor Vehicle Dept. Saint Paul, MN Title #C2210Q487		Registration issued or renewed - Loan or lien reported - Vehicle color noted as Gray
08/20/2014	161,141	Brausen Family Auto Saint Paul, MN 651-633-4100	≫	Vehicle serviced - Four wheel alignment performed - Oil and filter changed

9/21, 10:50 PM		CARFAX Vehicle Histor	ry Report for this	2003 SAAB 9-3 ARC: YS3FD46Y431055898
		▼ 5.0 / 5.0 8 Verified Reviews		- Drivability/performance checked - Alignment checked - Steering wheel centered - Tire condition and pressure checked - Steering/suspension checked - Brakes checked - Tires rotated
12/09/2014	163,949	Dale's Mobil 1 Loveland, CO 970-635-0200 dalesmobil1lube.com/ 5.0 / 5.0 <u>7 Verified Reviews</u>	×	Vehicle serviced - Oil and filter changed
01/10/2015		Dale's Mobil 1 Loveland, CO 970-635-0200 dalesmobil1lube.com/ 5.0 / 5.0 <u>7 Verified Reviews</u>	×	Vehicle serviced - Antifreeze/coolant flushed/changed
04/21/2015	165,865	Colorado Inspection Station		Passed emissions inspection
05/15/2015		Mike's Moonlight Auto Repair Greeley, CO 970-353-7915 2 Customer Favorites	×	Vehicle serviced
05/19/2015		Colorado Motor Vehicle Dept. Loveland, CO Title #06P219132		Title or registration issued - Registration updated when owner moved the vehicle to a new location
04/26/2016		Colorado Motor Vehicle Dept. Loveland, CO Title #06P219132		Registration issued or renewed
04/21/2017	172,978	Colorado Inspection Station		Passed emissions inspection
04/26/2017		Colorado Motor Vehicle Dept. Loveland, CO Title #06P219132		Registration issued or renewed
04/26/2018		Colorado Motor Vehicle Dept. Loveland, CO Title #06P219132		Registration issued or renewed - Title or registration issued
04/29/2019		Colorado Motor Vehicle Dept. Loveland, CO Title #06P219132		Title or registration issued
08/19/2019		Damage Report	į	Damage reported: minor damage - Damage to rear
				Damage Severity Scale i MINOR MODERATE SEVERE
CARFAX H ACCIDEN INFORMA	T & DAM			LEFT FRONT REAR

			Scratches to the vehicle body.
04/19/2021	199,859	Colorado Inspection Station	Passed emissions inspection
04/21/2021		Colorado Motor Vehicle Dept. Loveland CO	Registration issued or renewed

Have Questions? Consumers, please visit our Help Center at www.carfax.com. Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com.



Damage Indicator

Damage can be a result of many different types of events. Examples include contact with objects (other cars, trees, traffic signs, road debris, etc), vandalism, or weather-related events. Not every damage event is reported to CARFAX. As details about the damage event become available, those additional details are added to the CARFAX Vehicle History Report. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 9/30/21 at 12:50:24 AM (CDT). Other
information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle
inspection and test drive, to make a better decision about your next used car.

Damage Severity

Damage events result in one of the following severity levels:

- Minor: Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.
- Moderate: Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.
- Severe: Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

CARFAX recommends getting a pre-purchase inspection at a certified collision repair facility.

Title #06P219132

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Manufacturer Recall

Automobile manufacturers issue recall notices to inform owners of car defects that have come to the manufacturer's attention. Recalls also suggest improvements that can be made to improve the safety of a particular vehicle. Most manufacturer recalls can be repaired at no cost to you.

New Owner Reported

f

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:

facebook.com/CARFAX

@CARFAXinc C About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2021 CARFAX, Inc., a unit of IHS Markit Ltd. All rights reserved. 9/30/21 12:50:24 AM (CDT)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2003 SAAB 9-3 vehicle (VIN: YS3FD46Y431055898), which is based on information supplied to CARFAX and available as of 9/30/21 at 1:50 AM (EDT).

Customer Signature

Date

Dealer Signature

Date



SHOW ME THE CARFAX

© 2021 CARFAX, Inc., a unit of IHS Markit Ltd. All rights reserved. 9/30/21 12:50:24 AM (CDT)

CARFAX Warranty Check™

CARFAX has estimated the remaining original manufacturer warranty coverage based on information reported to us on this **2003 SAAB 9-3 ARC (YS3FD46Y431055898)**.

2003 SAAB 9-3 ARC		
VIN:	YS3FD46Y431055898	·
Estimated start date of warranty:	06/24/2003	
Last CARFAX reading reported on 04/19/2021:	199,859 miles	CAR
Today's Date:	09/30/2021	

Enter the current mileage and click 'Recalculate Warranty' to update the remaining warranty coverage.

Enter current mileage:

mi	Recalculate Warranty	
Type of Coverage	Original Warranty	Estimated Remaining Coverage
Basic	48 months or 50,000 miles	Coverage expired
Drivetrain	48 months or 50,000 miles	Coverage expired
Emissions	96 months or 80,000 miles	Coverage expired
Corrosion	72 months or unlimited mileage	Coverage expired
Transferable	No cost, unlimited owners covered	Same
Roadside Assistance	No data reported to CARFAX	
Safety belt & inflatable restraint	No data reported to CARFAX	
Specific Components	96 months or 80,000 miles	Coverage expired
Notes	Emissions: Manufacturer covers emissions components under basic warranty. Emissions coverage may vary by state. Refer to owners manual for specific details. Transferable: No cost, unlimited owners covered. Specific Components: Adjustments and wear item covered for 1/16,000. Maintenance: Most models receive no-charge manufacturer scheduled maintenance for 3/36,000. 9-2x receives 2/24,000 no-charge manufacturer scheduled maintenance. Notes: 9-3 and 9-3 Convertible 10/Unlimited corrosion coverage.	

CARFAX Warranty Check provides an estimate of this vehicle's remaining warranty coverage. It does not take into account some vehicle history events such

https://www.carfaxonline.com/vhrs/YS3FD46Y431055898

9/29/21, 10:50 PM

CARFAX Vehicle History Report for this 2003 SAAB 9-3 ARC: YS3FD46Y431055898

as some title brands that may void the original manufacturer warranty or ownership transfers that may decrease warranty coverage. This warranty information is only valid for vehicles manufactured for the United States. Complete warranty coverage information is available for this vehicle at the SAAB web site.





© 2021 CARFAX, Inc., an IHS company. All rights reserved. Patents pending. 09/30/2021 00:50:27