



551 N. Washington St.
Falls Church, VA 22046
Phone: (703) 534-0770

Invoice No.

48436

Page 1

Order Date 06/07/21 08:16 am
Closed/Paid: 06/24/21 10:47 am

PLEASE TAKE SOME TIME AND GIVE US A REVIEW ONLINE

BAKER, ROBERT
1443 CORCORAN ST. NW
WASHINGTON DC 22747
?: 202-462-1957

06 SAAB 9-3 SILVER

Odometer reading in: 75850 out: 75886/07/21 08:17am 0.00
Lic: FE-2565/DC Cyl 2.8 Eng
Vin: YS3FH71U566002726
Eq:

Quotes

ROBERT in person.

Last in 6/7/2021

Job01 CHECK ENGINE

Labor: \$650.00

12 763 086 Fuel Pump Assembly-N (List 494.87) 1.0 @ 494.87 =\$ 494.87 494.87

LAMP LIT NEEDS CODES PULLED P0089 CODE FAULTY FUEL PUMP PREESURE IN ADEQUATE NEEDS NEW PUMP

Job02 Intermediate Service 9-3SS V6

Labor: \$187.50

93186310	OIL FILTER INSER-N	1.0 @	16.48 =\$	16.48
3536966	Drain Plug Gasket-N	1.0 @	1.92 =\$	1.92
0221317	Synthetic Oil-N	7.0 @	7.25 =\$	50.75
93172129	COMPARTMENT FILTER-N (List 35.95)	1.0 @	35.00 =\$	35.00
0215830	Washer Fluid-N (List 4.33)	1.0 @	4.33 =\$	4.33
203	MI 3000-N	1.0 @	14.25 =\$	14.25
115	BG EXTENDED LIFE MOA-N (List 18.50)	1.0 @	15.75 =\$	15.75
				138.48

Visual safety inspection, Change engine oil and filter, Check and adjust tire pressure including spare, Check lights, Check and lubricate door hinges, latches and locks, Check battery condition, and clean terminals, Check washer fluid level, wiper blades and top up system, Check crank case ventilation system and vacuum lines, Check drive belts tensioners and idler pulleys, Check cooling system and hoses, Inspect brake system, Inspect brake system, pads and rotor condition, Inspect exhaust system, Inspect front and rear suspension, Inspect shock absorbers and bushings, Inspect inner and outer drive shaft joint boots, Rotate tires and inspect for uneven tire wear, Check and adjust parking brake, Check safety belts and SRS warning lights

Job03 FRT BRAKES

Labor: \$216.00

EUR972	Brake Pad Set-Front Cera-N (List 145.65) @	145.65 =\$	145.65
93 171 500	Brake Disc-Front-N (List 192.72)	1.0 @ 192.72 =\$	192.72
			338.37

FRT BRAKES BELOW MINIMUM WE REPLACED THE FRT PADS AND ROTORS

Job04 REAR BRAKES

Labor: \$0.00

AT 3.5 MM WILL NEED SOON EST 575 NEXT OIL AND FILTER 5000

Job05 INTERIOR

Labor: \$195.00

----->----->----->-----Continued on the next page----->----->----->----->



551 N. Washington St.
Falls Church, VA 22046
Phone: (703) 534-0770

Invoice No.
48436

Page 2
Order Date 06/07/21 08:16 am
Closed/Paid: 06/24/21 10:47 am

PLEASE TAKE SOME TIME AND GIVE US A REVIEW ONLINE

Job05 INTERIOR

13 192 013	Stepper Motor-N (List 170.70)	1.0 @	170.70 =\$	170.70	170.70
------------	-------------------------------	-------	------------	--------	--------

LOUD CLICKING FORM DASH HAS FAULTY RECIRC MOTOR

Job06 SUSPENSION

Labor: \$390.00

90538496	SPRING SUPPORT-N (List 12.12)	2.0 @	12.72 =\$	25.44	
12802494	BUMP STOP-N	2.0 @	27.30 =\$	54.60	80.04

REAR SPRING SEATS AND BUSHING DETERIORATED WE REPLACED THE SET BOTH SIDES

Job07 CONV TOP

Labor: \$455.00

12833507	SENSOR-N	1.0 @	133.15 =\$	133.15	133.15
----------	----------	-------	------------	--------	--------

IS INOP DUE TO FAULTY TONNEAU SENSOR WE REPLACED IT AND WHEN OPERATING THE TOP THE DR SIDE
RAMM FOR TONNEAU BLEW OUT FLUID.

Job08 TONNEAU RAMS

Labor: \$780.00

WE REPLACED BOTH THE DRIVERS AND PASSSIDE TONNEAU RAMS AND BLED THE SYSTEM

360-Paym.smt Date: 06/24/2021 10:47 CC Type: Amex CC#: XXXXXXXXXXXXX6005
Approval: 842686 WQ#: 000048436 Amount: 4360.80 MerchantID: OrderID:

Signature: _____

I agree to pay the total amount shown above in compliance with the
cardholder agreement.

Payments to IM Autohaus

Cost Summary

Status: Closed Work Order

Payments: \$4,360.80

1 06/24/21 4360.80 AMEX

H4ltr/p12kauEMsTT

Labor	2873.50
Parts	1355.61
Shop Supplies	42.75
Tax	88.94
Total	\$4360.80
Payments	4360.80
Bal Due	0.00

IM Autohaus Warranty:

Thank you for choosing IM Autohaus

All work performed by IM Autohaus has a 24,000 OR 24 month (which ever comes first) warranty on parts and labor. Warranty is only applicable for parts
purchased through IM Autohaus.

Disclaimer:

There is a minimum diagnostic fee of \$140.00. There is a \$35 a day storage unless prior arrangements are made. By signing this you are agreeing to
terms above. And also providing IM Autohaus permission to test drive your vehicle as needed.

Customer Signature _____

Date _____

play CARFAX in online listings: ☐



This report provided free of charge by:
IM Autohaus
551 N Washington St
Falls Church, VA 22046
(703) 5347222

2
Customer Favorites




Vehicle History Report™

US \$44.99

2006 SAAB 9-3 AERO

VIN: YS3FH71U566002726
CONVERTIBLE
2.8L I6 F SOHC
3ASOLINE
FRONT WHEEL DRIVE



11 Service history records

4 Previous owners

Personal vehicle

78,874 Last reported odometer reading

This CARFAX Report Provided by:
IM Autohaus
 2 Customer Favorites

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 12/3/23 at 12:34:29 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.



Ownership History

The number of owners is estimated

	Owners 1-2	Owner 3	Owner 4
Year purchased	2006	2016	2022
Type of owner	Personal	Personal	Personal
Estimated length of ownership	10 yrs. 4 mo.	5 yrs. 4 mo.	6 months
Owned in the following states/provinces	Texas, Texas	District of Columbia	Virginia, South Carolina
Estimated miles driven per year	See Details	1,192/yr	---
Last reported odometer reading	67,405	75,850	78,874



Title History

CARFAX guarantees the information in this section

	Owners 1-2	Owner 3	Owner 4
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem	<input checked="" type="checkbox"/> Guaranteed No Problem



GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify.
[View Terms](#) | [View Certificate](#)





Additional History



Not all accidents / issues are reported to CARFAX

	Owners 1-2	Owner 3	Owner 4
Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported


ARFAX recommends that you have this vehicle inspected by a collision repair specialist.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
irbag Deployment o airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported	<input checked="" type="checkbox"/> No Issues Reported
dometer Check o indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated	<input checked="" type="checkbox"/> No Issues Indicated	<input checked="" type="checkbox"/> No Issues Indicated
ccident / Damage ccident reported: 09/27/2015. Damage reported: 08/07/2017.	Very Minor Damage	Minor Damage	No New Issues Reported
anufacturer Recall o open recalls reported to CARFAX.	<input checked="" type="checkbox"/> No Recalls Reported	<input checked="" type="checkbox"/> No Recalls Reported	<input checked="" type="checkbox"/> No Recalls Reported
asic Warranty riginal warranty estimated to have expired.	Warranty Expired	Warranty Expired	Warranty Expired

<div> <div>CARFAX</div> <div>Detailed History</div> </div>			
<div> <div> <div> <div>Owner 1</div> <div>Purchased: 2006</div> </div> <div>  <div> <div>Low mileage!</div> <div>This owner drove less than the industry average of 15,000 miles per year.</div> </div> </div> <div> <div>Personal Vehicle</div> <div>5,707 mi/yr</div> </div> </div> </div>			
Date	Mileage	Source	Comments
04/10/2006	130	Texas Motor Vehicle Dept. Plano, TX	Title issued or updated <ul style="list-style-type: none"> -First owner reported -Titled or registered as personal vehicle -Loan or lien reported
03/01/2007		Texas Motor Vehicle Dept. Plano, TX	Registration issued or renewed <ul style="list-style-type: none"> -Loan or lien reported -Passed safety inspection
03/01/2008		Texas Motor Vehicle Dept. Plano, TX	Registration issued or renewed <ul style="list-style-type: none"> -Loan or lien reported -Passed safety inspection
03/22/2008	11,826	Texas Inspection Station Plano, TX	Passed emissions inspection
03/01/2009		Texas Motor Vehicle Dept. Plano, TX	Title issued or updated <ul style="list-style-type: none"> -Registration issued or renewed -Loan or lien reported -Passed safety inspection
03/30/2009	17,495	Texas Inspection Station Plano, TX	Passed emissions inspection
09/15/2009		Texas Motor Vehicle Dept.	Vehicle purchase reported
09/19/2009	20,077	Online Listing	Vehicle offered for sale
09/21/2009	20,078	Texas Inspection Station Plano, TX	Passed emissions inspection
09/26/2009		Texas Motor Vehicle Dept. Flower Mound, TX	Registration issued or renewed <ul style="list-style-type: none"> -Passed safety inspection
<div> <div> <div>Owner 2</div> <div>Purchased: 2009</div> </div> <div>  <div> <div>Low mileage!</div> <div>This owner drove less than the industry average of 15,000 miles per year.</div> </div> <div> <div>Personal Vehicle</div> <div>7,507 mi/yr</div> </div> </div> </div>			
Date	Mileage	Source	Comments

		Texas Motor Vehicle Dept. Flower Mound, TX		This record is updated - New owner reported
09/24/2010	29,806	Texas Inspection Station Flower Mound, TX		Passed emissions inspection
10/01/2010		Texas Motor Vehicle Dept. Flower Mound, TX		Registration issued or renewed - Passed safety inspection
09/22/2011	39,958	Texas Inspection Station Flower Mound, TX		Passed emissions inspection
10/01/2011		Texas Motor Vehicle Dept. Flower Mound, TX		Registration issued or renewed - Passed safety inspection
09/29/2012	47,271	Texas Inspection Station Flower Mound, TX		Passed emissions inspection
10/01/2012		Texas Motor Vehicle Dept. Flower Mound, TX		Registration issued or renewed - Passed safety inspection
09/28/2013	54,493	Texas Inspection Station Flower Mound, TX		Passed emissions inspection
10/01/2013		Texas Motor Vehicle Dept. Flower Mound, TX		Registration issued or renewed - Passed safety inspection
08/25/2014		National Tire & Battery Grapevine, TX 214-513-1800 ntb.com ★ 4.5 / 5.0 50 Verified Reviews ♥ 42 Customer Favorites	✂	Vehicle serviced - Electrical system checked
09/13/2014	61,391	Texas Inspection Station Flower Mound, TX		Passed emissions inspection
10/01/2014		Texas Motor Vehicle Dept. Flower Mound, TX		Registration issued or renewed - Passed safety inspection
01/08/2015	63,556	Southwest Auto Dallas, TX 972-488-2525 southwestauto.com ★ 4.8 / 5.0 33 Verified Reviews ♥ 17 Customer Favorites	✂	Vehicle serviced - Oil and filter changed - Tires rotated - Cabin air filter replaced/cleaned - Spark plug(s) replaced - Drive belt(s) replaced - Engine/powertrain computer/module checked
01/23/2015		Southwest Auto Dallas, TX 972-488-2525 southwestauto.com ★ 4.8 / 5.0 33 Verified Reviews ♥ 17 Customer Favorites	✂	Vehicle serviced - Brake fluid flushed/changed
05/20/2015	65,664	Southwest Auto Dallas, TX 972-488-2525 southwestauto.com ★ 4.8 / 5.0	✂	Vehicle serviced - Antifreeze/coolant checked - Drive belts checked - Brakes checked - Oil and filter changed


09/12/2015	67,302	Texas Inspection Station Flower Mound, TX	Failed emissions inspection
09/25/2015	67,381	Southwest Auto Dallas, TX 972-488-2525 southwestauto.com ★ 4.8 / 5.0 33 Verified Reviews ♥ 17 Customer Favorites	 Vehicle serviced - Spark plug(s) replaced - Cabin air filter replaced/cleaned - Oil and filter changed - Tires rotated - Drive belt(s) replaced - Fluids checked - Engine/powertrain computer/module checked
09/26/2015	67,405	Texas Inspection Station Flower Mound, TX	Passed emissions inspection
09/27/2015		Damage Report	 Accident reported: very minor damage - Damage to front


**CARFAX HAS THE MOST
ACCIDENT & DAMAGE
INFORMATION**



Minor damage is usually cosmetic, including dents or scratches to the vehicle body.

10/01/2015	Texas Motor Vehicle Dept. Flower Mound, TX	Registration issued or renewed - Passed safety inspection
------------	--	---





Owner 3
 Purchased: 2016




Low mileage! This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle
 1,192 mi/yr

Date	Mileage	Source	Comments
09/01/2016		Virginia Motor Vehicle Dept.	Vehicle purchase reported
09/08/2016	70,190	D.C. Motor Vehicle Dept. Washington, DC	Odometer reading reported
09/08/2016		D.C. Motor Vehicle Dept.	Title issued or updated - New owner reported
09/14/2016		D.C. Inspection Station	Passed emissions inspection

09/15/2016		D.C. Motor Vehicle Dept. Washington, DC		Registration issued or renewed
08/01/2017	71,146	K & W International Swedish Falls Church, VA 703-534-0770 ★ 4.8 / 5.0 16 Verified Reviews	✖	Vehicle serviced
08/07/2017		Damage Report	i	Damage reported: minor damage - Damage to front
<div>CARFAX HAS THE MOST ACCIDENT & DAMAGE INFORMATION</div> <div><div>Minor damage is usually cosmetic, including dents or scratches to the vehicle body.</div></div>				
10/22/2017		D.C. Motor Vehicle Dept. Washington, DC		Registration issued or renewed
07/30/2018	71,838	K & W International Swedish Falls Church, VA 703-534-0770 ★ 4.8 / 5.0 16 Verified Reviews	✖	Vehicle serviced
09/12/2018		D.C. Inspection Station Washington, DC		Passed emissions inspection
09/12/2018		D.C. Motor Vehicle Dept. Washington, DC		Registration issued or renewed
11/04/2018	72,716	K & W International Swedish Falls Church, VA 703-534-0770 ★ 4.8 / 5.0 16 Verified Reviews	✖	Vehicle serviced
06/07/2020	74,996	K & W International Swedish Falls Church, VA 703-534-0770 ★ 4.8 / 5.0 16 Verified Reviews	✖	Vehicle serviced - Oil and filter changed - Battery/charging system checked - Cooling system checked

06/07/2021		75,850	K & W International Swedish Falls Church, VA 703-534-0770 ★ 4.8 / 5.0 16 Verified Reviews		Vehicle serviced - Cooling system checked - Oil and filter changed - Brakes checked - Lights checked - Tire condition and pressure checked - Rear suspension checked - Steering/suspension checked - Safety inspection performed - Door locks checked - Battery/charging system checked - Parking brake adjusted - Parking brake system checked - Exhaust system checked - Tires rotated
08/24/2021			D.C. Motor Vehicle Dept. Washington, DC	Registration issued or renewed	
 Owner 4 Purchased: 2022					Personal Vehicle
Date	Mileage	Source	Comments		
01/07/2022	76,870	Virginia Motor Vehicle Dept. Weems, VA	Title or registration issued - New owner reported		
01/13/2022	76,872	Virginia Inspection Station	Passed safety inspection		
08/01/2022		South Carolina Motor Vehicle Dept.	Vehicle purchase reported		
08/23/2022	77,851	South Carolina Motor Vehicle Dept. Hilton Head Island, SC	Title issued or updated - Registration issued or renewed - Registration updated when owner moved the vehicle to a new location		
09/08/2022	77,927	Express Oil Change & Tire Engineers Bluffton, SC 843-919-0616 https://expressoil.com/stores/bluffton/sc/3021/ ★ 4.9 / 5.0 82 Verified Reviews ❤️ 3 Customer Favorites		Vehicle serviced - Maintenance inspection completed - Oil and filter changed	
08/15/2023		South Carolina Motor Vehicle Dept. Hilton Head Island, SC	Registration issued or renewed		
10/15/2023		South Carolina Motor Vehicle Dept. Hilton Head Island, SC	Title issued or updated		
11/14/2023	78,874	Virginia Inspection Station	Passed safety inspection		
Have Questions? Consumers, please visit our Help Center at www.carfax.com . Dealers or Subscribers, please visit our Help Center at www.carfaxonline.com .					

Glossary

Accident Indicator

CARFAX receives information about accidents in all 50 states, the District of Columbia and Canada.

Report. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

- According to the National Safety Council, Injury Facts, 2021 edition, 5% of the 276 million registered vehicles in the U.S. were involved in an accident in 2019. Over 77% of these were considered minor or moderate.
- This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 12/3/23 at 12:34:29 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

Damage Indicator

Damage can be a result of many different types of events. Examples include contact with objects (other cars, trees, traffic signs, road debris, etc), vandalism, or weather-related events. Not every damage event is reported to CARFAX. As details about the damage event become available, those additional details are added to the CARFAX Vehicle History Report. CARFAX recommends that you have this vehicle inspected by a qualified mechanic.

- This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 12/3/23 at 12:34:29 PM (CST). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

Damage Severity

Damage events result in one of the following severity levels:

- Minor: Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.
- Moderate: Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.
- Severe: Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

CARFAX recommends getting a pre-purchase inspection at a certified collision repair facility.

Failed Emissions Inspection

A failed emissions check performed during a vehicle inspection indicated the vehicle was emitting more than allowable emissions standards and/or had missing or modified parts. Repeated failed emissions records can indicate engine problems and CARFAX recommends you have the vehicle inspected.

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

New Owner Reported

When a vehicle is sold to a new owner, the Title must be transferred to the new owner(s) at a Department of Motor Vehicles.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide an estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:  facebook.com/CARFAX  [@CARFAXinc](https://twitter.com/CARFAXinc)  [About CARFAX](#)

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

©2023 CARFAX, Inc., part of S&P Global. All rights reserved.
12/3/23 12:34:29 PM (CST)

I have reviewed and received a copy of the CARFAX Vehicle History Report for this 2006 SAAB 9-3 vehicle (VIN: YS3FH71U566002726), which is based on information supplied to CARFAX and available as of 12/3/23 at 1:34 PM (EST).

Customer Signature	Date	Dealer Signature	Date
--------------------	------	------------------	------